

SERVICE BULLETIN

UTILITY TRAILER MANUFACTURING CO.



SB-08-186

Issue date: June 9th, 2015

Bendix ACom Diagnostic Software

To request the latest download of [ACom Diagnostic Software](#), follow the Bendix link and submit your information.

The ACom User Guide is located on www.utm.com in the Operation & Service Manuals subset. Please follow this link to view the [ACom User Guide](#).

Please utilize the list below of Service Engineers by region if you have any questions regarding the ACom Diagnostic Software.

Service Engineers by Region

All of Canada

Wayne Thomas: 905.401.1012
Wayne.Thomas@Bendix.com

North East

(MN,VT,NH,NY,NJ,MA,RI,CT,PA,DE&MD)

Martin Pytlak: 570.460.5437
Martin.Pytlak@Bendix.com

East Central

(IL,IN,OH,WV,VA&OH)

Bob Pawluk: 248.634.4030
Robert.Pawluk@Bendix.com

South West

(CA,NV,UT,CO,NM,AZ&HI)

Paul Jones: 755.353.4266
Paul.Jones@Bendix.com

South East

(TX,OK,AR,LA,MS,AL,TN,NC,SC,GA&FL)

Brian Screeton: 260.229.8801
Brian.Screeton@Bendix.com

North Central

(IL,IN,OH,WV,VA&OH)

Bob Pawluk: 248.634.4030
Robert.Pawluk@Bendix.com

North West

(WA,WY,MT,ID,OR&Alaska)

Chuck Miller: 425.844.9242
Charles.Miller@Bendix.com



SERVICE BULLETIN



UTILITY TRAILER MANUFACTURING CO.

RP1210 Adapters

The Bendix ACom Diagnostic Software relies on RP1210 compliant hardware adapters for communication.

NOTE: ACom Diagnostics will remain in the demo mode unless there is at least one RP1210 driver installed on the computer.

Before using this software, verify that the driver (.dll) for the adapter to be used for communications is already loaded on the computer and is the latest version available from the adapter manufacturer.

Recommended Adapters

- [NAVCom/NAVLink](#)
- Volvo 88890020
- [Nexiq USB-Link 2](#)
- Nexiq Bluetooth USB-Link
- [Nexiq PLC Adapter](#)
- [Noregon DLA+](#)
- [Noregon DLA+PLC](#)
- Noregon UDIF PLC/J1708
- JPRO DLA+PLC
- [Cummins Inline 5](#)
- [Cummins Inline 6](#)
- [Dearborn DPA4+](#)
- [Dearborn DPA5](#)
- Dearborn PLC TestCon (may be available in a kit with DPA4+)

****Note: Adapters that interface using serial or parallel ports to the laptop are no longer supported.**

Any other questions regarding this service bulletin should be directed to Utility's Field Service Department at 800-423-6591.

Field Service Department
UTILITY TRAILER MANUFACTURING COMPANY