



SERVICE BULLETIN NO. SB-11-004

Issue date: 10/09

SUBJECT: Introduction of UTM Repair Procedure for Removing and replacing a 3000R (VS1/2/3RA) roof skin. See RP-11-010.

Utility Trailer Mfg Co. has released a repair procedure for the removal and replacement of a reefer roof skin for VS1RA, VS2RA, and VS3RA model trailers.

Information regarding Repair Procedure RP-11-010 can be obtained at your local Utility dealer or by contacting Utility Trailer Mfg. Co. (Field Service Dept):

Customer Note:

Any repairs considered to be warranty must be performed at a repair facility designated by Utility Trailer Mfg. Co.

A list of dealers in your area can be obtained by clicking the link below:

[\(Dealer Locator\)](#)

Any questions regarding this service bulletin should be directed to Utility's Field Service Department at 800-423-6591.

Field Service Department

UTILITY TRAILER MANUFACTURING COMPANY