

# SERVICE BULLETIN



UTILITY TRAILER MANUFACTURING CO.

## SB-08-160

Issue date: April 16, 2013

### Hub Cap Compatibility with the Hendrickson Precision 320 & 240 Spindle Nut

Refer to the following information when changing hub-caps on any trailer that utilizes the Hendrickson Precision 320 & 240 spindle nuts.

- For HN-Spindle (Tapered spindle) see the following Hendrickson Service Bulletin [Precision 240 Spindle Nut System Compatibility](#)
- For HP-Spindle (Parallel Spindle) see the following Hendrickson Service Bulletin [Precision 320 Spindle Nut System Compatibility](#)
- For HN or HP Spindle with Meritor PSI the only compatible hub-caps are as follows:

Spindle	Lube	UTM OE PN:	Federal Mogul PN:
HN-Spindle With PSI	(Grease)	3-1560-39	N/A
HN-Spindle With PSI	(Oil)	NA	HWM-650

Spindle	Lube	UTM OE PN:	Federal Mogul PN:
HP-Spindle With PSI	(Grease)	3-1560-40	N/A
HP-Spindle With PSI	(Oil)	NA	HWM-195-45

Any other questions regarding this service bulletin should be directed to Utility's Field Service Department at 800-423-6591.

Field Service Department  
UTILITY TRAILER MANUFACTURING COMPANY

Utility hasn't independently evaluated the information contained in the attached technical bulletin; it is making the bulletin available as a convenience and for information purposes. You are encouraged to contact Hendrickson at (866) 743-3247 if you have any questions concerning the content of the document, or how these issues affect trailers you are servicing.